

HAER
MD
1-CUMB.V,
5-

HISTORIC AMERICAN ENGINEERING RECORD INDEX TO PHOTOGRAPHS

WESTERN MARYLAND RAILWAY BRIDGE

(Spring Gap Underpass)

HAER No. MD-115

Spanning MD Route 51 at Spring Gap

Cumberland vicinity

Allegany County

Maryland

Photographer: Rob Tucher

Photographic Documentation

July 22, 1995

- MD-115-1 East elevation showing context and approach looking west
- MD-115-2 West elevation showing context and approach looking east
- MD-115-3 East elevation looking southwest
- MD-115-4 West elevation looking northeast
- MD-115-5 Abandoned railway bed looking northwest
- MD-115-6 West elevation, north abutment and northern two railing panels, looking northeast
- MD-115-7 East elevation, south abutment looking south
- MD-115-8 West elevation, west end of north wing wall, looking north
- MD-115-9 West elevation, west end of south wing wall, south abutment and south railing panel looking east
- MD-115-10 West elevation, west end of north wing wall, top of north abutment and oblique of railing panels looking northwest
- MD-115-11 West elevation, detail of top of south abutment and south end post looking northwest
- MD-115-12 West elevation, detail of north end post looking northwest

KEY TO PHOTOGRAPHS
WESTERN MARYLAND RAILWAY BRIDGE
(Spring Gap Underpass)
HAER No. MD-115 (Page 2)

